sigrist photometer

LabScat 2

How to order?



	1	2	3	4	5	6	7
Photometer Product variants and sets							
	LabScat 2 with 50 mm cuvette			**LabScat 2**		**Sets with 50 mm, 25 mm cuvette**	
	+ control unit + calibration certificate + 1x cuvette KPL50/190 for temperature control + Cooling set +	+ control unit + calibration certificate + 1x cuvette KPL50/190 + Cooling set	+ control unit + calibration certificate + 1x cuvette KPL50/190	+ control unit + calibration certificate		+ control unit + calibration certificate + 1x cuvette KLP50/190 + 1x cuvette KLP25/190 + Cuvette KLP 50/190 for temperature control + Cooling set+ Calibration up to 500 EBC–25mm cuvette, including certificate	+ control unit + calibration certificate + 1x cuvette KLP50/190 + 1x cuvette KLP25/190 Calibration up to 500 EBC–25mm cuvette, including certificate
							
Communication							
USB, Ethernet, Modbus TCP	122774	122770	122766	119185	124293	123120	122778
+ Modbus RTU	122775	122771	122767	122763		123121	122779
+ Profibus DP	122776	122772	122768	122764		123122	122780
+ Profinet IO	122777	122773	122769	122765		123123	122781

Cooling set: Fan for cooling operation
Cooling set+: Fan for cooling operation, temperature sensor for controlling the measurement; additional required: cooling unit (E.g. Julabo Corio-CD-200F)

Accessories

+	111786	Cuvette KPL50/190 only for LabScat with temperature control
+	114114	Cuvette KPL50/190 glass with lock LabScat 2
+	119468	Cuvette KPL25/190 glass with lock LabScat 2
+	119461	Ethernet cable: LabScat 2
+	119462	USB cable: LabScat 2
+	112653	Water filter for LabScat 2
+	119202	Desiccant bag, 50 g
+	119470	Control unit

Doc. No 16524E/6