

LabScat 2

How to order?



1

2

3

4

5

6

7

Photometer product variants and sets						
Sets with or without 50 mm cuvette				Sets with 50 mm and 25 mm cuvette		
LabScat 2 with + checking unit + 2x cuvette KPL50/190 (for labscat with temp-control only) Temperature control system Accessories kit for cooling operation (fan to avoid condensation)	LabScat 2 + checking unit + 2x cuvette KPL50/190	LabScat 2 + checking unit + 2x cuvette KPL50/190	LabScat 2 + checking unit	2x cuvette KLP50/190 1x cuvette KLP25/190 25 mm Temperature control cuvette KPL50/190 (for labscat with temp-control only) Temperature control system Accessories kit for cooling operation (fan to avoid condensation) Calibration up to 500 EBC - 25mm cuvette, incl. certificate	2x cuvette KLP50/190 1x cuvette KLP25/190 25 mm Accessories kit for cooling operation (fan to avoid condensation) Calibration up to 500 EBC - 25mm cuvette, incl. Certificate	2x cuvette KLP50/190 1x cuvette KLP25/190 25 mm Calibration up to 500 EBC - 25mm cuvette, incl. certificate
122774	122770	122766	119185	123120	122782	122778
122775	122771	122767	122763	123121	122783	122779
122776	122772	122768	122764	123122	122784	122780
122777	122773	122769	122765	123123	122785	122781

IO: 0/4..20 mA

